From: Eduardo Alcantara Jr < lalojr8978@gmail.com>

Sent: Thursday, March 26, 2015 4:09 PM

To:Way, StevenCc:Brian LamoriaSubject:26MAR15

Attachments: South Muddy River.bmp; North Muddy River.bmp; Bird Dog Club.bmp; BD_RightBank south

border.jpg; BD RightBank(deadfish).jpg; BD RightBank.jpg; BD RightBank Northborder.jpg;

LB NorthBorder.jpg; LB SouthBorder.jpg

Steve,

The maps attached show the areas requested by Jeff to be surveyed.

Bird Dog Club was completed after our phone conversation today. I have attached pictures of this. No oil observed only that brownish natural stain. We had an encounter with a beaver, and I've attached a picture of one dead fish on the right bank. The area had 02 fishermen on site, they relayed to us that they have been catching fish there recently with no problems.

We will continue SCAT operations with STANTEC tomorrow and through the weekend clearing up the remaining segments.

Respectfully,

PO2 Eduardo Alcantara